

# 2022 CHEVROLET CORVETTE SERVICE MANUAL

- **SEARCH**

1. **HVAC**


2. **Heating, Ventilation, and Air Conditioning**

3. **Repair Instructions**


- 4.

## Instrument Panel Outer Air Outlet Replacement - Left Side

### Removal Procedure




1. [Click here for full size](#)
2. Remove the left body hinge pillar garnish molding (1).Body Hinge Pillar Garnish Molding Replacement




3.  
[Click here for full size](#)

4. Remove the left windshield garnish molding (2). Windshield Garnish Molding Replacement




5.  
[Click here for full size](#)

6. Remove the left instrument panel trim pad radio speaker opening cover (1). Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement




7.  
[Click here for full size](#)

8. Remove the left radio front speaker grille molding (2).Radio Front Speaker Grille Molding Replacement




9.  
[Click here for full size](#)

10. Remove the left instrument panel outer trim cover (1).Instrument Panel Outer Trim Cover Replacement




11.  
[Click here for full size](#)

12. Instrument Panel Accessory Bezel (2) >> Remove - Instrument Panel Accessory Bezel Replacement




13.  
[Click here for full size](#)

14. Instrument Panel Instrument Cluster Hood (1) >> Remove - Instrument Panel Instrument Cluster Hood Replacement




15.  
[Click here for full size](#)

16. Instrument Panel Cluster Trim Plate (1) >>> Remove - Instrument Panel Cluster Trim Plate Replacement




17.  
[Click here for full size](#)

18. Instrument Panel Knee Bolster (2) >>> Remove - Instrument Panel Knee Bolster Replacement



19.  
[Click here for full size](#)


20. Instrument Panel Air Outlet Bezel - Left Side (2) >> Remove - Instrument Panel Air Outlet Bezel Replacement - Left Side




21.  
[Click here for full size](#)

22. Instrument Panel Outer Air Outlet (1) >> Remove


## Installation Procedure



1. [Click here for full size](#)
2. Instrument Panel Outer Air Outlet (1) >> Install




3. [Click here for full size](#)
4. Instrument Panel Air Outlet Bezel - Left Side (2) >> Install - Instrument Panel Air Outlet Bezel Replacement - Left Side




5.  
[Click here for full size](#)

6. Instrument Panel Knee Bolster (2) >> Install - Instrument Panel Knee Bolster Replacement




7.  
[Click here for full size](#)

8. Instrument Panel Cluster Trim Plate (1) >> Install - Instrument Panel Cluster Trim Plate Replacement




9.  
[Click here for full size](#)

10. Instrument Panel Instrument Cluster Hood (1) >> Install - Instrument Panel Instrument Cluster Hood Replacement




11.  
[Click here for full size](#)

12. Instrument Panel Accessory Bezel (2) >> Install - Instrument Panel Accessory Bezel Replacement




13.  
[Click here for full size](#)

14. Install the left instrument panel outer trim cover (1).Instrument Panel Outer Trim Cover Replacement




15.  
[Click here for full size](#)

16. Install the left radio front speaker grille molding (2).Radio Front Speaker Grille Molding Replacement




17. [Click here for full size](#)

18. Install the left instrument panel trim pad radio speaker opening cover (1).Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement



19. [Click here for full size](#)

20. Install the left windshield garnish molding (2).Windshield Garnish Molding Replacement



21. [Click here for full size](#)
22. Install the left body hinge pillar garnish molding (1).Body Hinge Pillar Garnish Molding Replacement

mcx30.com