

2022 CHEVROLET CORVETTE SERVICE MANUAL

- [SEARCH](#)

1. [HVAC](#)


2. [Heating, Ventilation, and Air Conditioning](#)

3. [Repair Instructions](#)

- 4.

Radio Cooling Duct Replacement (Right Hand Drive)

Removal Procedure




1. [Click here for full size](#)

2. Note:

Left hand drive vehicle shown, right hand drive vehicle similar.

3. Instrument Panel Compartment (1) >> Remove - Instrument Panel Compartment Replacement



4. [Click here for full size](#)

5. Note:

Left hand drive vehicle shown, right hand drive vehicle similar.

6. Floor Front Air Outlet Duct - Right Side (1) >> Remove - Floor Front Air Outlet Duct Replacement - Right Side

7. [Click here for full size](#)

8. Radio Cooling Duct Bolt (1) >> Remove [2x]

9. [Click here for full size](#)

10. Radio Cooling Duct (1) >> Remove

Installation Procedure

1. [Click here for full size](#)


2. Radio Cooling Duct (1) >> Install

3. [Click here for full size](#)

4. Caution:


Refer to Fastener Caution.

5. Radio Cooling Duct Bolt (1) >> Install and tighten [2x] 1.5 N-m (13 lb in)



6.
[Click here for full size](#)

7. Floor Front Air Outlet Duct - Right Side (1) >> Install - Floor Front Air Outlet Duct Replacement - Right Side



8.
[Click here for full size](#)

9. Instrument Panel Compartment (1) >> Install - Instrument Panel Compartment Replacement