


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH


1. HVAC
2. [HVAC - Automatic](#)
3. [Repair Instructions](#)
- 4.

Air Conditioning Evaporator Air Temperature Sensor Replacement

Removal Procedure



1.
[Click here for full size](#)
2. Remove the left and right instrument panel outer trim cover (1). Instrument Panel Outer Trim Cover Replacement



3.
[Click here for full size](#)
4. Instrument Panel Knee Bolster (2) >> Remove - Instrument Panel Knee Bolster Replacement