


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. HVAC
- 2. HVAC - Automatic
- 3. Repair Instructions
- 4.

Inside Air Moisture and Windshield Temperature Sensor Replacement



Click here for full size
Windshield Multifunction Sensor Mount Bracket Cover Replacement

Callout	Component Name
Preliminary Procedure	
1	Inside Air Moisture and Windshield Temperature Sensor Procedure 1. Unlatch the inside air moisture and windshield temperature sensor from the front view driver information camera bracket. 2. Disconnect the electrical connector.