

2022 CHEVROLET CORVETTE SERVICE MANUAL

- **SEARCH**

1. **Power and Signal Distribution**

2. **Wire and Connector Repair**

3. **Repair Instructions**

- 4.

0.5 NANO, 1.2 MCON Series Connectors

Special Tools

- J-38125-215A
- EL-38125-58

For equivalent regional tools, refer to Special Tools.

Connector Removal Procedure

1. Click here for full size
2. Slide the CPA to the released position by sliding it away from the component.
3. Click here for full size
4. While depressing the connector latch, gently pull the connector from the component.

Terminal Removal Procedure

1. Click here for full size
2. Note:

The wire tie MUST be cut above wire dress tab to prevent damage to wires.

3. Remove the wire cover by carefully cutting the wire tie with side cutters.
4. Click here for full size
5. Use a small flat blade screwdriver to release the retention tabs of the wire cover and then lift the cover off the connector assembly.
6. Click here for full size
7. Insert a small screwdriver under the TPA and gently pry it open.

8.

Other List:graphic

- (1) 0.5 mm terminal
- (2) 0.5 Terminal Release Access
- (3) 1.2 Terminal Release Access
- (4) 1.2 mm terminal

9. This connector has 2 different size terminals, release access holes and terminal tools. The terminal size and release access holes can be identified in the image above.

10.

Other List:graphic

- 0.5 terminal release tool EL-38125-58
- Click here for full size
- 1.2 terminal release tool J-38125-215A