


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Body Repair](#)
- 2. [Bolted Exterior Body Panels and Closures](#)
- 3. [Repair Instructions](#)
- 4.

Back Body Opening Frame Side Filler Replacement



Click here for full size
Fastener Caution.

Tighten

23N-m (17 lb ft)

Callout	Component Name
1	Back Body Opening Frame Side Filler Bolt [2x]
	Caution:
	Refer to
2	Back Body Opening Frame Side Filler