

2022 CHEVROLET CORVETTE SERVICE MANUAL

- **SEARCH**

1. **Roof**
2. **Folding Top**
3. **Repair Instructions**
- 4.

Folding Top Front Latch Striker Replacement

Click here for full size

Windshield Upper Garnish Molding Replacement

Fastener Caution.

Tighten

22N-m (16 lb ft)

Callout	Component Name
Preliminary Procedure	
1	Folding Top Front Latch Striker Bolt [2x] Caution: Refer to
2	Folding Top Front Latch Striker Procedure 1. Using a grease pencil, outline various contours of the folding top front latch sticker to insure proper reinstallation. 2. Disconnect the electrical connector.