

2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

1. Roof
2. **Folding Top**
3. **Repair Instructions**
- 4.

Folding Top Side Intermediate Weatherstrip Replacement

Click here for full size

Quarter Window Trim Finish Panel Replacement

-

Body Side Upper Rear Applique Replacement

Fastener Caution.

Tighten

2.5N-m (22 lb in)

Callout	Component Name
	Preliminary Procedures 1.
1	Folding Top Side Intermediate Weatherstrip Retainer Bolt [2x] Caution: Refer to
2	Folding Top Side Intermediate Weatherstrip Procedure 1. Clean the mounting area using a lint-free cloth dampened with a 50/50 mixture of isopropyl alcohol and water. 2. Water test and inspect the folding top for proper operation.