

2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

1. Roof

2. **Folding Top**

3. **Repair Instructions**

- 4.

Folding Top Side Rail Garnish Molding Replacement

Click here for full size

Folding Top and Folding Top Stowage Compartment Lid Operation Warning.

Warning:

Refer to

Folding Top Stowage Compartment Lid Heat Warning.

Caution:

Refer to

Folding Top Guidelines Caution.

Preliminary Procedure

Operate the folding top to the halfway open position.

Folding Top and Folding Top Stowage Compartment Lid Operation

Fastener Caution.

Procedure

1. If NEW threaded components are being installed, loosen the adhesive using a metal pick or similar tool before proceeding. If threaded components are reused, prepare the threaded components using the following steps:
2.
 1. Remove any loose cured adhesive from the external threads of the components using a lint free cloth.
 2. Thread the cleaned components into the internal mating threads and remove to loosen trapped cured adhesive.
 3. Apply thread locking adhesive to the external threads of the components.

Adhesives, Fluids, Lubricants, and Sealers

- Ensure there are no gaps in the thread locking adhesive once applied to the component.

Tighten

1.8N-m (16 lb in)

Callout	Component Name
Warning:	
Refer to	
1	Folding Top Side Rail Garnish Molding Bolt [2x] Caution: Refer to
2	Folding Top Side Rail Garnish Molding