

2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

1. [Roof](#)
2. [Folding Top](#)
3. [Repair Instructions](#)
- 4.

Folding Top Stowage Compartment Lid Adjustment

Warning:

When the folding top or folding top stowage compartment lid is opening or closing, personal injury may occur by the parts in motion. Ensure all individuals involved maintain a safe distance from these parts while operating to avoid any personal injury or vehicle damage

1. Folding Top Stowage Compartment Lid Bracket Nut >> Loosen [6x]
2. Folding Top Stowage Compartment Lid Hinge Bolt >> Loosen [4x]
3. [Click here for full size](#)
4. Adjust the rear compartment lid in order to obtain an even gap between the lid and the folding top stowage compartment lid, quarter outer panel, and the rear bumper fascia and so that the lid is flush with the folding top stowage compartment lid, quarter outer panel, and the rear bumper fascia.
5.
 - Folding top stowage compartment lid to roof (a) 8.0 mm $\tilde{\Delta}\pm 1.25\text{ mm}$ (0.31 in $\tilde{\Delta}\pm 0.05\text{ in}$)
 - Folding top stowage compartment lid to rear quarter outer panel (b) 3.5 mm $\tilde{\Delta}\pm 1.25\text{ mm}$ (0.14 in $\tilde{\Delta}\pm 0.05\text{ in}$)
 - Folding top stowage compartment lid to rear compartment lid (c) 4.5 mm $\tilde{\Delta}\pm 1.0\text{ mm}$ (0.17 in $\tilde{\Delta}\pm 0.04\text{ in}$)
6. Caution:
Refer to Fastener Caution.
7. Folding Top Stowage Compartment Lid Bracket Nut >> Tighten [6x] 22N-m (16 lb ft)
8. Folding Top Stowage Compartment Lid Hinge Bolt >> Tighten [4x] 25N-m (18 lb ft)
9. Adjust the folding top stowage compartment lid bumpers as necessary.