

2022 CHEVROLET CORVETTE SERVICE MANUAL

- **SEARCH**

1. **Roof**

2. **Folding Top**

3. **Repair Instructions**

4.

Folding Top Stowage Compartment Lid Mechanism Upper Cover Replacement

Click here for full size

Folding Top Stowage Compartment Lid Mechanism Lower Cover Replacement

Fastener Caution.

Tighten

2.5N-m (22 lb in)

Callout	Component Name
Preliminary Procedure	
1	Quarter Upper Trim Panel Bracket Bolt [3x] Caution: Refer to
2	Folding Top Stowage Compartment Lid Mechanism Upper Cover