


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Roof
- 2. Removable Top
- 3. Repair Instructions
- 4.

Roof Lift Off Panel/Window Front Striker Replacement



Click here for full size
Windshield Upper Garnish Molding Replacement

- Using a grease pencil, outline various contours of the roof lift off panel/window front striker.

Fastener Caution.

Tighten

22N-m (16 lb ft)

Callout	Component Name
Preliminary Procedures	
1.	
1	Roof Lift Off Panel/Window Front Striker Bolt [2x] Caution: Refer to

Callout	Component Name
2	Roof Lift Off Panel/Window Front Striker Procedure 1. If equipped, disconnect the electrical connector. 2. Align the roof lift off panel/window front striker to the grease pencil markings. 3. Clean the mounting area from all grease pencil markings.