


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Roof
- 2. Removable Top
- 3. Repair Instructions
- 4.

Roof Lift Off Panel/Window Latch Handle Replacement



Click here for full size
Roof Lift Off Panel Replacement

Fastener Caution.

Tighten

18N-m (13 lb ft)

Callout	Component Name
Preliminary Procedure	
1	Roof Lift Off Panel/Window Latch Handle Bolt
	Caution:
	Refer to
2	Roof Lift Off Panel/Window Latch Handle