


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Roof
- 2. Removable Top
- 3. Repair Instructions
- 4.

Roof Lift Off Panel/Window Latch Trim Cover Replacement



[Click here for full size Roof Lift Off Panel Replacement](#)

Fastener Caution.

Tighten

3>N-m (27 lb in)

Callout	Component Name
Preliminary Procedure	
1	Roof Lift Off Panel/Window Latch Trim Cover Bolt [2x] Caution: Refer to
2	Roof Lift Off Panel/Window Latch Trim Cover Procedure Using a suitable plastic trim tool, release the retaining tabs.