


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Roof
- 2. Removable Top
- 3. Repair Instructions
- 4.

Roof Lift Off Panel/Window Rear Locating Pin Replacement



Click here for full size
Roof Lift Off Panel Replacement

Fastener Caution.

Tighten

24N-m (18 lb ft)

Callout	Component Name
Preliminary Procedure	
	Roof Lift Off Panel/Window Rear Locating Pin [2x]
1	Caution: Refer to