


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Roof](#)
- 2. [Removable Top](#)
- 3. [Repair Instructions](#)
- 4.

Roof Lift Off Panel/Window Rear Locator Replacement



[Click here for full size](#)
Quarter Window Trim Finish Panel Replacement

- Using a grease pencil, outline various contours of the roof lift off panel/window rear locator.
-

Roof Lift Off Panel/Window Rear Locator Bracket Replacement

Fastener Caution.

Tighten

10N-m (89 lb in)

Callout	Component Name
Preliminary Procedures	
1.	
1	Roof Lift Off Panel/Window Rear Locator Bolt [2x] Caution: Refer to

Callout	Component Name
2	Roof Lift Off Panel/Window Rear Locator Procedure 1. Align the roof lift off panel/window rear locator to the grease pencil markings. 2. Clean the mounting area from all grease pencil markings.

mcx30.com