


# 2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Roof
- 2. Removable Top
- 3. Repair Instructions
- 4.

## Roof Lift Off Panel/Window Rear Striker Replacement



Click here for full size  
Headlining Rear Trim Panel Replacement

- Using a grease pencil, outline various contours of the roof lift off panel/window rear striker.

Fastener Caution.

Tighten

9>N-m (80 lb in)

| Callout                | Component Name                                                                    |
|------------------------|-----------------------------------------------------------------------------------|
| Preliminary Procedures |                                                                                   |
| 1.                     |                                                                                   |
| 1                      | Roof Lift Off Panel/Window Rear Striker Bolt [2x]<br><br>Caution:<br><br>Refer to |
|                        |                                                                                   |

| Callout | Component Name                                                                                                                                                                                                                                                                                                                                                                                                         |
|---------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 2       | <p data-bbox="180 125 580 147">Roof Lift Off Panel/Window Rear Striker</p> <p data-bbox="240 181 344 203">Procedure</p> <ol data-bbox="209 237 976 327" style="list-style-type: none"> <li data-bbox="209 237 976 271">1. Align the roof lift off panel/window rear striker to the grease pencil markings.</li> <li data-bbox="209 293 976 327">2. Clean the mounting area from all grease pencil markings.</li> </ol> |

mcx30.com