


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Roof](#)
- 2. [Removable Top](#)
- 3. [Repair Instructions](#)
- 4.

Roof Lift Off Panel/Window Stowage Rear Bracket Replacement



[Click here for full size](#)
Rear Compartment Front Lower Partition Replacement

Fastener Caution.

Tighten

9>N-m (80 lb in)

Callout	Component Name
Preliminary Procedure	
1	Roof Lift Off Panel/Window Stowage Rear Bracket Nut [2x] Caution: Refer to
2	Roof Lift Off Panel/Window Stowage Rear Bracket