


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Safety and Security](#)
- 2. [Driver Assistance Systems](#)
- 3. [Repair Instructions](#)
- 4.

Side Object Sensing Alert Module Shield Replacement



[Click here for full size](#)
Rear Bumper Fascia Removal and Installation

Callout	Component Name
Preliminary Procedure	
1	Side Object Sensing Alert Module Shield Retainer [2x]
2	Side Object Sensing Alert Module Shield