


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Safety and Security](#)
- 2. [Remote Functions](#)
- 3. [Repair Instructions](#)
- 4.

Low Frequency Front Bumper Antenna Replacement



[Click here for full size](#)
Front Bumper Fascia Lower Stiffener Replacement

Callout	Component Name
Preliminary Procedure	
1	Low Frequency Antenna Retainer [2x]
2	Low Frequency Front Bumper Antenna
	Procedure
	Disconnect the electrical connector.