


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Safety and Security
- 2. Remote Functions
- 3. Repair Instructions
- 4.

Remote Function Actuator Module Replacement



[Click here for full size](#)
Rear End Trim Cover Panel Replacement

Callout	Component Name
Preliminary Procedure	
1	Remote Control Door Lock Receiver Procedure 1. Disconnect the electrical connector. 2. Push up on the lower retaining tab, pull down and forward to remove.