


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

1. Safety and Security
2. Supplemental Restraints
3. Repair Instructions
- 4.

Airbag Front End Discriminating Sensor Replacement



[Click here for full size
SIR Warning](#)

Warning:

Refer to

SIR Inflator Module Handling and Storage Warning.

Warning:

Following the deployment of a side impact air bag, inspect the following parts for damage. Replace these parts if necessary:

- The seat cushion frame
- The seat recliner, if equipped
- The seat adjuster
- The seat back frame

Failure to do so may cause future personal injury.

Preliminary Procedures

1. Disable the SIR system

SIR Disabling and Enabling