


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Safety and Security
- 2. Supplemental Restraints
- 3. Repair Instructions
- 4.

Restraints Control Module Replacement



Click here for full size
SIR Warning

Preliminary Procedures

- 1. Disable the SIR system

SIR Disabling and Enabling

-

Front Floor Console Compartment Replacement

Fastener Caution.

Tighten

9 N-m (80 lb in)

Control Module References

- Enable the SIR System.

SIR Disabling and Enabling

Callout	Component Name

Callout	Component Name
Warning: Do not strike or jolt the Restraints Control Module (RCM). Before applying power to the RCM, make sure that it is securely fastened. Failure to observe the correct installation procedure could cause Supplemental Inflatable Restraint (SIR) deployment, personal injury, or unnecessary SIR system repairs. Warning: Refer to	
1	Airbag Sensing and Diagnostic Module Nut [3x] Caution: Refer to
2	Restraints Control Module Procedure 1. Disconnect the electrical connectors. 2. Perform the necessary programming and setup procedure: