

2022 CHEVROLET CORVETTE SERVICE MANUAL


- **SEARCH**

1. **Safety and Security**
2. **Theft Deterrent**
3. **Repair Instructions**
- 4.

Content Theft Deterrent Sensor Replacement

Removal Procedure

1. Windshield Upper Garnish Molding >> Remove - Windshield Upper Garnish Molding Replacement



2.
Click here for full size
3. Release the retaining tabs on the content theft deterrent sensor (1).
4. Disconnect the electrical connector.
5. Content Theft Deterrent Sensor (1) >> Remove

Installation Procedure