


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Seats
- 2. Power Seats
- 3. Repair Instructions
- 4.

Front Seat Back Lumbar Replacement



[Click here for full size](#)
Front Seat Back Cushion Finish Panel Replacement

Eye Protection Warning.

Procedure

Drill out the rivets.

Callout	Component Name
Preliminary Procedure	
1	Front Seat Back Lumbar Rivet [4x]
	Warning:
	Refer to
2	Front Seat Back Lumbar Retainer [6x]

Callout	Component Name
3	Front Seat Back Lumbar Procedure 1. Disconnect the electrical connector. 2. Release the two cable tie retainers holding the seat back lumbar pump to the seat back frame. 3. Disengage the lumbar from the seat back frame.

mcx30.com