


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Seats](#)
- 2. [Power Seats](#)
- 3. [Repair Instructions](#)
- 4.

Front Seat Recliner Actuator Motor Replacement



[Click here for full size](#)
Front Seat Back Cushion Finish Panel Replacement

Eye Protection Warning.

Procedure

- 1. Remove the rivet in the end of the rod.
- 2. Gently tap the recliner rod outward until the rod is free of the recliner motor.

Fastener Caution.

Tighten

6 N-m (53 lb in)

Callout	Component Name
Preliminary Procedure	
1	Front Seat Recliner Actuator Shaft
	Warning:
	Refer to

Callout	Component Name
2	Front Seat Recliner Actuator Motor Bolt Caution: Refer to
3	Front Seat Recliner Actuator Motor Procedure Disconnect the electrical connector.

mcx30.com