


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Seats
- 2. Seat Hardware, Trim, and Upholstery
- 3. Repair Instructions
- 4.

Front Seat Back Cushion Finish Panel Replacement (AQ9)



[Click here for full size](#)
Front Seat Back Cover and Pad Replacement

Fastener Caution.

Tighten

2 N-m (18 lb in)

Callout	Component Name
Preliminary Procedure	
1	Front Seat Back Cushion Finish Panel Screw [6x] Caution: Refer to
2	Front Seat Back Cushion Finish Panel Procedure 1. Release the retainers. 2. Transfer components as necessary.