


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Seats
- 2. [Seat Hardware, Trim, and Upholstery](#)
- 3. [Repair Instructions](#)
- 4.

Front Seat Cushion Frame Replacement



[Click here for full size](#)
Front Seat Adjuster Replacement

Front Seat Recliner Actuator Replacement

- Clean the thread locking compound from the bolts and reapply new thread locker. The bolts are held in by Blue 242Å,Å® medium strength loctite.

Callout	Component Name
Preliminary Procedure	
1	Front Seat Recliner Actuator Bolt - Lower [6x] Procedure 1. Remove the lower bolts from both sides.

Callout	Component Name
2	Driver or Passenger Seat Cushion Frame Procedure 1. Disconnect and reposition harness as necessary. 2. Disengage the cushion frame from the recliner tracks by pushing inward on the recliner tracks and sliding the cushion frame forward. 3. Transfer components as necessary.