


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Repair
- 2. Bolted Exterior Body Panels and Closures
- 3. Repair Instructions
- 4.

Fuel Tank Filler Pipe Housing Replacement



[Click here for full size](#)
Fuel Tank Filler Door Replacement

- Quarter Outer Panel Replacement - Left Side

Fastener Caution.

Tighten

9>N-m (80 lb in)

Callout	Component Name
Preliminary Procedures	
1.	
1	Fuel Tank Filler Pipe Housing Nut[3x] Caution: Refer to

Callout	Component Name
2	Fuel Tank Filler Pipe Housing Note: When replacing the fuel tank filler pipe housing with a new housing, a new label is required to be added to the new filler pipe housing Procedure 1. Disconnect the electrical connector. 2. Ensure the fuel tank filler pipe housing and seal is full seated to the filler pipe.

mcx30.com