


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Repair
- 2. Bolted Exterior Body Panels and Closures
- 3. Repair Instructions
- 4.

Liftgate Hinge Replacement



Click here for full size
Roof Panel Rear Extension Replacement

•

Liftgate Replacement

- Mark the position of the hinges with a grease pencil.

Fastener Caution.

Tighten

22N-m (16 lb ft)

Callout	Component Name
Preliminary Procedures	
1.	
1	Liftgate Hinge Nut [4x]
	Caution: Refer to
2	Liftgate Hinge [2x]
	Procedure Adjust the rear compartment lid as needed.