


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. **Body Repair**
- 2. **Bolted Exterior Body Panels and Closures**
- 3. **Repair Instructions**
- 4.

Liftgate Replacement



Click here for full size
Rear Compartment Lid Hold-Open Device Warning.

Preliminary Procedures

- 1.

Underhood Lamp Replacement

-

Rear Closure Center Applique Replacement

-

Liftgate Strut Replacement

Fastener Caution.

Tighten

25N-m (18 lb ft)

Callout	Component Name
Warning:	
Refer to	
	Rear Compartment Lid Bolt [4x]
1	Caution:
	Refer to

Callout	Component Name
2	Rear Compartment Lid Procedure 1. Disconnect the electrical connector. 2. With the aid of an assistant, remove the rear compartment lid. 3. Transfer components as necessary.

mcx30.com