


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Body Repair](#)
- 2. [Bolted Exterior Body Panels and Closures](#)
- 3. [Repair Instructions](#)
- 4.

Load Floor Panel Rear Cross Bar Replacement - Left Side (Coupe)



[Click here for full size](#)
[Back Body Opening Frame Side Filler Replacement](#)

Fastener Caution.

Tighten

23N-m (17 lb ft)

Callout	Component Name
Preliminary Procedure	
	Load Floor Panel Rear Cross Bar Bolt [2x]
1	Caution: Refer to
2	Load Floor Panel Rear Cross Bar