


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. **Body Repair**
- 2. **Bolted Exterior Body Panels and Closures**
- 3. **Repair Instructions**
- 4.

Load Floor Panel Rear Cross Bar Replacement - Right Side (Convertible)



[Click here for full size](#)
Rear Window Panel Replacement

- Release the harness retainer. { If equipped }

Fastener Caution.

Tighten

23N-m (17 lb ft)

Callout	Component Name
Preliminary Procedures	
1.	
1	Load Floor Panel Rear Cross Bar Bolt [4x]
	Caution:
	Refer to
2	Load Floor Panel Rear Cross Bar