

2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

1. Body Repair

2. Bolted Exterior Body Panels and Closures

3. Repair Instructions

- 4.

Rear Compartment Lid Adjustment

1. Rear Compartment Lid Hinge Nut >> Loosen [4x]
2. [Click here for full size](#)
3. Adjust the rear compartment lid in order to obtain an even gap between the lid and the folding top stowage compartment lid, quarter outer panel, and the rear bumper fascia and so that the lid is flush with the folding top stowage compartment lid, quarter outer panel, and the rear bumper fascia.
4.
 - Rear compartment lid to folding top stowage compartment lid (a) 4.5 mm $\tilde{\Delta}\pm 1.0$ mm (0.17 in $\tilde{\Delta}\pm 0.03$ in)
 - Rear compartment lid to rear quarter outer panel (b) 3.5 mm $\tilde{\Delta}\pm 1.25$ mm (0.14 in $\tilde{\Delta}\pm 0.05$ in)
 - Rear compartment lid to rear bumper fascia (c) 4.0 mm $\tilde{\Delta}\pm 1.25$ mm (0.16 in $\tilde{\Delta}\pm 0.05$ in)
5. Caution:
Refer to Fastener Caution.
6. Rear Compartment Lid Hinge Nut >> Tighten [4x]22N-m (16 lb ft)
7. Adjust the rear compartment lid bumpers as necessary.