

2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

1. Body Repair

2. Bolted Exterior Body Panels and Closures

3. Repair Instructions

- 4.

Rear Compartment Lid Hinge Replacement

[Click here for full size](#)

Rear Compartment Lid Replacement

Fastener Caution.

Tighten

25 N-m (18 lb ft)

Callout	Component Name
Preliminary Procedure	
1	Rear Compartment Lid Hinge Bolt [2x] Caution: Refer to
2	Note: If replacing the rear compartment lid hinge, the new hinge will need to be drilled using 11mm drill prior to installation. Use dimpled locations marked on the new hinge. Rear Compartment Lid Hinge