

2022 CHEVROLET CORVETTE SERVICE MANUAL

- **SEARCH**

1. **Body Repair**

2. **Bolted Exterior Body Panels and Closures**

3. **Repair Instructions**

- 4.

Rear Compartment Lid Replacement

Click here for full size

Fastener Caution.

Tighten

22 N-m (16 lb ft)

Rear Compartment Lid Adjustment

Callout	Component Name
1	Rear Compartment Lid Nut [4x] Caution: Refer to
2	Rear Compartment Lid Procedure 1. With the aid of an assistant, remove the rear compartment lid. 2. Rear Compartment Lid >> Adjust -