

2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Body Repair](#)
- 2. [Bolted Exterior Body Panels and Closures](#)
- 3. [Repair Instructions](#)
- 4.

Rear Compartment Lid Strut Replacement

Click here for full size
Rear Compartment Lid Hold-Open Device Warning.

Procedure

- 1. Release the lock tabs on the strut.
- 2. Ensure the clip is fully seated when the rod is reinstalled. If the clip cannot be fully seated, a new rod should be installed.

Callout	Component Name
1	Rear Compartment Lid Strut
	Warning:
	Refer to