


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Repair
- 2. Bolted Exterior Body Panels and Closures
- 3. Repair Instructions
- 4.

Rear Floor Panel Rear Extension Replacement - Left Side



[Click here for full size](#)
Fuel Tank Strap Replacement - Left Side

- Auxiliary Fuel Tank Shield >> Reposition -

Auxiliary Fuel Tank Shield Replacement - Left Side

- Support the fuel tank with a suitable jack.

Fastener Caution.

Tighten

22 N-m (16 lb ft)

Callout	Component Name
Preliminary Procedures	
1.	
1	Rear Floor Panel Rear Extension Bolt [6x] Caution: Refer to
2	Rear Floor Panel Rear Extension