


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Body Repair](#)
- 2. [Bolted Exterior Body Panels and Closures](#)
- 3. [Repair Instructions](#)
- 4.

Rear Floor Panel Rear Extension Replacement - Right Side



Click here for full size
Fuel Tank Strap Replacement - Right Side

- Support the fuel tank with a suitable jack.
- Remove the 8 auxiliary fuel tank shield bolts

Auxiliary Fuel Tank Shield Replacement - Right Side

Fastener Caution.

Tighten

22 N-m (16 lb ft)

Callout	Component Name
Preliminary Procedures	
1.	
1	Rear Floor Panel Rear Extension Bolt [6x]
	Caution:
	Refer to
2	Rear Floor Panel Rear Extension