


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. **Body Repair**
- 2. **Bolted Exterior Body Panels and Closures**
- 3. **Repair Instructions**
- 4.

Roof Panel Rear Extension Replacement



Click here for full size
Roof Lift Off Panel/Window Rear Weatherstrip Retainer Replacement

Fastener Caution.

Tighten

2.5N-m (22 lb in)

Callout	Component Name
Preliminary Procedure	
1	Roof Panel Bolt [6x] Caution: Refer to
2	Roof Panel Rear Extension