


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Body Repair](#)
- 2. [Bumpers and Fascias](#)
- 3. [Repair Instructions](#)
- 4.

Exhaust Tail Pipe Heat Sleeve Replacement



[Click here for full size](#)
[Eye Protection Warning.](#)

Preliminary Procedure

Rear Bumper Fascia Removal and Installation

Callout	Component Name
Warning:	
Refer to	
1	Exhaust Tail Pipe Heat Sleeve Rivet [4>x] Procedure Drill out the rivets.
2	Exhaust Tail Pipe Heat Sleeve