


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Body Repair](#)
- 2. [Bumpers and Fascias](#)
- 3. [Repair Instructions](#)
- 4.

Front Bumper Fascia Center Support Replacement



[Click here for full size](#)
[Front Headlamp Replacement](#)

[Front Headlamp Replacement](#)

Fastener Caution.

Tighten

9>N-m (80 lb in)

Callout	Component Name
Preliminary Procedure	
1	Headlamp Bolt [2x]
	Procedure
	Remove the headlamp bolts.
2	Front Bumper Fascia Center Support Bolt [4x]
	Caution:
	Refer to
3	Front Bumper Fascia Center Support