


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Repair
- 2. Bumpers and Fascias
- 3. Repair Instructions
- 4.

Front Bumper Fascia Energy Absorber Replacement



Click here for full size
Front Bumper Fascia Removal and Installation

- Disconnect the electrical connector and reposition the wiring harness.

Fastener Caution.

Tighten

9>N-m (80 lb in)

Callout	Component Name
Preliminary Procedures	
1.	
1	Front Bumper Fascia Energy Absorber Bolt [4x] Caution: Refer to
2	Front Bumper Fascia Energy Absorber Procedure Transfer components as necessary.