


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Body Repair](#)
- 2. [Bumpers and Fascias](#)
- 3. [Repair Instructions](#)
- 4.

Front Bumper Fascia Guide Replacement - Inner



[Click here for full size](#)
[Front Headlamp Replacement](#)

Fastener Caution

Tighten

2.5 N-m (22 lb in)

Callout	Component Name
Preliminary Procedure	
1>	Front Bumper Fascia Guide Bolt [2>x] Caution :
2>	Front Bumper Fascia Guide