


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Body Repair](#)
- 2. [Bumpers and Fascias](#)
- 3. [Repair Instructions](#)
- 4.

Front Bumper Fascia Lower Support Replacement



[Click here for full size Front Bumper Fascia Removal and Installation](#)

Fastener Caution.

Tighten

9>N-m (80 lb in)

Callout	Component Name
Preliminary Procedure	
1	Front Bumper Fascia Center Support Nut Caution: Refer to
2	Front Bumper Fascia Lower Support