


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Body Repair](#)
- 2. [Bumpers and Fascias](#)
- 3. [Repair Instructions](#)
- 4.

Front Bumper Lower Fascia Replacement



[Click here for full size](#)
[Front Bumper Fascia Removal and Installation](#)

- Place the front bumper fascia down on a clean protected surface.
- Disconnect the electrical connector.

Fastener Caution.

Tighten

2.5N-m (22 lb in)

Callout	Component Name
Preliminary Procedures	
1.	
1	Front Bumper Fascia Bolt [10x] Caution: Refer to
2	Front Bumper Fascia Bolt [2x] Tighten 2.5N-m (22 lb in)

Callout	Component Name
3	Front Bumper Lower Fascia Procedure 1. Reposition the wiring harness. 2. Release the retainer tabs. 3. Transfer components as necessary.

mcx30.com