

2022 CHEVROLET CORVETTE SERVICE MANUAL

- **SEARCH**

1. **Body Repair**
2. **Bumpers and Fascias**
3. **Repair Instructions**
- 4.

Rear Bumper Fascia Diffuser Replacement

Removal Procedure

1. Raise the vehicle.
2. Click here for full size
3. Rear Bumper Fascia Diffuser Bolt (1) >> Remove [4x]
4. Underbody Rear Air Deflector Bolt (2) >> Remove [10x]
5. Rear Wheelhouse Panel Liner Bolt (3) >> Remove [2x]
6. Rear Bumper Fascia Retainer (4) >> Remove [2x]
7. Click here for full size
8. Rear Bumper Fascia Diffuser (1) >> Remove

Installation Procedure

1. Click here for full size
2. Rear Bumper Fascia Diffuser (1) >> Install
3. Click here for full size
4. Rear Bumper Fascia Retainer (4) >> Install [2x]
5. Caution:
Refer to Fastener Caution.
6. Rear Wheelhouse Panel Liner Bolt (3) >> Install and tighten [2x]2.5N-m (22 lb in)
7. Underbody Rear Air Deflector Bolt (2) >> Install and tighten [10x]2.5N-m (22 lb in)
8. Rear Bumper Fascia Diffuser Bolt (1) >> Install and tighten [4x]2.5N-m (22 lb in)
9. Lower the vehicle.