


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Repair
- 2. Bumpers and Fascias
- 3. Repair Instructions
- 4.

Rear Bumper Lower Fascia Bracket Replacement



[Click here for full size](#)
Underbody Rear Air Rear Deflector Replacement

Fastener Caution.

Tighten

9>N-m (80 lb in)

Callout	Component Name
Preliminary Procedure	
1	Rear Bumper Lower Fascia Bracket Bolt [3x] Caution: Refer to
2	Rear Bumper Fascia Retainer
3	Rear Bumper Lower Fascia Bracket