


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Repair
- 2. Bumpers and Fascias
- 3. Repair Instructions
- 4.

Rear Bumper Lower Fascia Replacement



Click here for full size
Rear Bumper Fascia Removal and Installation

- Reposition the wiring harness.

Fastener Caution.

Tighten

2.5 N-m (22 lb in)

Callout	Component Name
Preliminary Procedures	
1.	
1	Rear Bumper Fascia Bolt [2x]
	Caution: Refer to
2	Rear Bumper Fascia Clip [18x]
3	Rear Bumper Lower Fascia
	Procedure
Transfer components as necessary.	