


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Repair
- 2. Frame and Underbody
- 3. Repair Instructions
- 4.

Floor Panel Tunnel Panel Reinforcement Replacement



Click here for full size
Lifting and Jacking the Vehicle

Fastener Caution

Tighten

22N-m (16 lb ft)

Callout	Component Name
Preliminary Procedure	
1	Floor Panel Tunnel Panel Reinforcement Bolt @ Mid Tunnel [6>x] Caution: Refer to
2	Rear Cradle Brace Bolt [2>x] Procedure Loosen the rear cradle brace bolts. Tighten 160N-m (118thinsp;lb ft)

Callout	Component Name
3	Floor Panel Tunnel Panel Reinforcement Procedure 1. Remove the 6 floor panel tunnel panel reinforcement bolts (1). 2. Slide the floor panel tunnel panel reinforcement rearward, into the opening.

mcx30.com